

# V700 FW 25.4.1.8 - Release Notes

Compatible with WiFi Base release version 25.4.1.3

Compatible with Transfer Station release version 25.4.1.1

Compatible with Smart Control release version 25.4.1

Changes since version 25.3.1

## New Feature: Peer Assisted Recording (PAR)

- When configured, V700 will support PAR recording start triggers to and from other PAR enabled devices when in close proximity.

## Improvements:

- Error 604 will not be reported to the user. Hotspot connection will be tried infinitely when not available.

## Fixes:

MVDES-2203	BWC Will not upload events
G2WEAR-11740	Error 604 will not be reported to the user. Hotspot connection will be tried infinitely when not available.

## Known issues:

G2WEAR-11776	PAR not triggering camera to record if recording quickly restarted Mitigation: N/A
G2WEAR-11771	PAR config accepts negative values Mitigation: User can modify the configuration in the VM

G2WEAR-11597	Audio clips at certain sound decibel/frequencies  Mitigation: N/A
G2WEAR-11318	LiveStreaming does not work over wifi when LTE is preferred but not available.  Mitigation: N/A
G2WEAR-11319	LTE interface still has default route and IP even with no LTE signal.  Mitigation: N/A

## Notes:

- When PAR is configured with No beacon timeout, it defaults to 5 minutes.
- On checkout, pairing with APX radios may have to be redone if V700 does not reconnect automatically.
- If a V700 is docked in a transfer station and the slot config changes from static IP to the DHCP, if V700 does not connect to EL, V700 needs to be power cycled.
- Pairing information can be lost or overwritten if two cameras are checked out to the same officer at the same time and the officer attempts to pair with both of the cameras in succession. If this happens, pairing will need to be forgotten from the phone and the camera will need to be re-paired using the dual button press.
- This V700 release should be used with SmartControl phone application 25.3.1 or later.
- This V700 release should be used with SmartControl suite 25.3.1 or later. (PC application)
- For APX Next interoperability, the APX NEXT needs to have FW version R04.20.00 or later
- When pairing a V700 with an iOS phone, if the phone was previously paired to that V700, the pairing information has to be forgotten in the iOS settings on the iPhone before you are able to pair with that V700 again.
- Very large RATF requests can cause V700 to reboot.
- The SmartControl player may fail to load on occasion. Retrying should fix the issue.
- USB uploads may take up to 5 minutes to start if V700 was undocked from a WiFi base and docked to USB base quickly
- Smart Control pairing can occasionally fail on the first attempt, a retry will succeed. If the retry fails, power cycle the camera.
- USB base connectivity to EL/ELC requires provisioning first.
- When a V700 is part of a group and associated with a WiFi base, if the WiFi icon is not present, dock/undock or power cycle V700.

- When removing the pairing information on V700 (dual button press) but not on the APX radio, pairing may fail. The workaround is to manually remove V700 from the APX radio device list and try again.
- When paired with an APX radio, WiFi association times are longer.